





Prepared by:



Figure 2
Gaps in the Watermaster's Current Groundwater-Level Monitoring Network